

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11244

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080021-0

RECEIVED FROM

DATE REC'D. 2-11-59

P.O. NO.

VENDOR PACKING SLIP NO.

| CHARGE TO QUANTITY RECEIVED | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | ACCT. OR W.O. NO. S.O. NO. |
|-----------------------------------|------------------------------|-------------------|-----------------------------------|--------------|------------|-----------------|-----------------|---------------------|----------------------------------|
| | 322 | | 41 | 0 | 10 | | | | |
| 96 | DRAWING NO. AND DESCRIPTION | | | | | | QUANTITY | | REMARKS |
| | 731410- B Connector Modified | | | | | | ACCEPTED | REJECTED | |
| | Ship per #35927 | | | | | | 96 | | |

W. E. Bond
J. E. Bond

RECEIVED
BYINSPECTED
BY

Date 2/12/59

REJECTS RETURNED
ON SHIP. MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

No. 11247

2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 2-12-59

P.O. NO.

VENDOR PACKING SLIP NO.

| CHARGE TO QUANTITY RECEIVED | CONTRACT CODE NO. | DRAWING NUMBER | DWG. DASH OR STANDARD PART NO. | DWG. REV. | LOT NO. | CLASS NUMBER | OPER. NUMBER | BUY OUT CODE NO. | ACCT. OR W.O. NO. S.O. NO. |
|-----------------------------------|-----------------------------|-------------------|-----------------------------------|--------------|------------|-----------------|-----------------|---------------------|----------------------------------|
| | 323 | | 17 | B | 11 | 1 | | | |
| 12 | DRAWING NO. AND DESCRIPTION | | | | | | QUANTITY | | REMARKS |
| | 731455-2 Spring Lamp | | | | | | ACCEPTED | REJECTED | |
| | Ship per #35928 | | | | | | 12 | | |

W. E. Bond
J. E. Bond

RECEIVED
BYINSPECTED
BY

Date 2/12/59

REJECTS RETURNED
ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080021-0